


Brackets can be mounted either way round dependant on required equipment orientation.  
Both brackets must be mounted in the same orientation.  
Torx T10 sized screw driver is required.

**These brackets are NOT to be used with any other Ampetronic equipment.**

Can be fitted to  
ILD122/300

BOX OUTLINE  
FOR REFERENCE



WML1U DRILLING TEMPLATE  
USE No8 ROUND HEAD SCREWS

UNIT MAY BE MOUNTED  
HORIZONTALLY OR VERTICALLY